

IMPORTANT

AVERTISSEMENT DE SÉCURITÉ

Climatiseur mobile QLIMA

PH 534

EAN 8713508777344



SPECIFICATIONS

MOBILE AIRCONDITIONER

Qlima

Model	PH 534
Cooling / Heating capacity *	3.2 kW / 2.9 kW
EE Class*	A
EER *	2.6
COP Class *	A+
COP*	2.7
Mains voltage	230 V - / 50 Hz / 1 Ph
Current	5.3 A
Power consumption in cooling mode	1.23 kW
Power consumption in heating mode	1.04 kW
Sound power level	65 dB(A)
Unit protection	IP X0
Pressure suction / discharge	12 / 23 (max. 23) bar
Refrigerant charge / GWP	R290 / 260 g / 3
CO ₂ equivalent	0.001 tonnes
Net weight	31 kg
Serial number	A1

* conform EN 14511

Distributed in Europe by PVG Holding B.V.,

P.O. Box 96, 5340 AB OIS, The Netherlands, Qlima.com



Qlima PH 534
Contains fluorinated greenhouse gases
covered by the Kyoto Protocol.
Refrigerant: R290: 260g / GWP: 3
Hermetically sealed

Refrigerant leakage contributes to
climate change. Refrigerant with lower
global warming potential (GWP) would
contribute less to global warming than
a refrigerant with higher GWP, if leaked to
the atmosphere.

Il est apparu qu'un certain nombre de climatiseurs mobiles PH 534 présentait un défaut de fabrication. Dans certains cas, un câble d'alimentation n'est pas correctement positionné.

Dans certaines circonstances, cela peut provoquer un court-circuit dans l'appareil. Dans des situations extrêmes, principalement en raison de l'utilisation d'une connexion non mise à la terre, l'apparition d'une flamme peut faire fondre les pièces en plastique et provoquer une fumée dense.

Si vous possédez ce produit, arrêtez de l'utiliser et débranchez l'appareil immédiatement. Prenez une photo de la plaque signalétique et notez le numéro de série. L'appareil doit ensuite être stocké dans une pièce bien ventilée, d'une surface minimale de 4 m² et à l'abri de toute source de feu/étincelles.

Contactez ensuite PVG France en envoyant de préférence un mail à PH534@pvg.eu (ou en appelant le 0232960747) pour nous communiquer votre nom, adresse complète, téléphone fixe et mobile ainsi que le numéro de série de l'appareil. Nous pourrions alors vérifier si votre produit doit être révisé.

En raison des limitations dues à l'épidémie de COVID-19, il se peut qu'il soit difficile de nous joindre ou que le délai de traitement de votre demande ne soit pas aussi rapide qu'il le devrait. Veuillez accepter nos sincères excuses si c'est le cas, et pour le désagrément occasionné.